## Tree Inventory and Preservation Plan Report 1794 Appleview Road Pickering, Ontario

prepared for

**Almont Homes Inc.** 

prepared by



146 Lakeshore Road West PO Box 1267 Lakeshore W PO Oakville ON L6K 0B3 t: 289.837.1871 e: consult@kuntzforestry.ca

15 September 2025

KUNTZ FORESTRY CONSULTING INC Project P4728

#### Introduction

Kuntz Forestry Consulting Inc. was retained by Almont Homes Inc. to complete a Tree Inventory and Preservation Plan as part of a development application for the property located at 1794 Appleview Road in Pickering, Ontario. The property is located on the east side of Appleview Road, west of Goldenridge Road within a residential area.

The work plan for this tree preservation study included the following:

- Prepare inventory of the tree resources over 15cm DBH on and within six metres
  of the Long Term Stable Top of Bank, and trees of all sizes within the road rightof-ways;
- Evaluate potential tree saving opportunities based on proposed development plans; and
- Document the findings in a Tree Inventory and Preservation Plan Report.

The results of the evaluation are provided below.

## Methodology

The tree inventory was conducted on 1 August 2025. The trees were located using the topographic survey provided for the property and estimations made in-field. Trees located on the subject property were tagged using the numbers \_\_\_\_. Trees that could not be tagged were identified as letters A-D. Polygons (groups of trees) were identified as P1-P3. Tree locations are shown on Figure 1. Refer to Table 1 for the tree inventory and Appendix A for photographs of the trees.

Tree resources were assessed utilizing the following parameters:

**Tree #** - number assigned to tree that corresponds to Figure 1.

**Species** - common and botanical names provided in the inventory table.

**DBH** - diameter (centimetres) at breast height, measured at 1.4 m above the ground.

**Condition** - condition of tree considering trunk integrity, crown structure, and crown vigour. Condition ratings include poor (P), fair (F) and good (G).

**Dripline** – radius of crown (metres), as measured from the centre of the stem to the outermost branches.

**Height** – approximate height of tree (metres), estimated from the base to the topmost branches

**Comments** - additional relevant detail.

#### **Existing Site Conditions**

The subject property is currently occupied by a single-storey dwelling, with landscaping features and a gravel driveway providing access to Appleview Road. Refer to Figure 1 for existing conditions.

#### Tree Resources

The tree inventory documented 70 trees and three tree polygons on and within six metres of the subject property. Refer to Figure 1 for location of trees.

Tree resources were comprised of White Spruce (*Picea glauca*), Manitoba Maple (*Acer negundo*), Sugar Maple (*Acer saccharum*), Apple species (*Malus spp.*), Black Walnut (*Juglans nigra*), White Mulberry (*Morus alba*), Silver Maple (*Acer saccharinum*), Little-leaf Linden (*Tilia cordata*), Horsechestnut (*Aesculus hippocastanum*), Austrian Pine (*Pinus nigra*), Norway Maple (*Acer platanoides*), and Eastern White Cedar (*Thuja occidentalis*).

## **Proposed Development**

The proposed development includes the demolition of the existing dwelling and construction of three new dwellings. The existing gravel driveway providing access to Appleview is to be removed, and the proposed dwellings are to front on to Goldenridge Road. Refer to Figure 1 for the existing conditions and proposed site plan.

#### **Discussion**

The following sections provide a discussion and analysis of development impacts, tree removal requirements, and tree preservation relative to the proposed development and existing conditions.

Development Impacts/Tree Removals

The proposed development will require the removal of 11 trees, including Trees 170-176, and 178-181. All trees identified for removal either directly conflict with the proposed building footprints or driveways.

The removal of an additional four trees, including Trees 167, 182, 185 and 199, are recommended regardless of the site plan due to their poor condition.

Refer to Figure 1 for the location of trees identified for removal.

#### Tree Preservation

The preservation of the remaining trees will be possible with the use of appropriate tree protection measures as indicated on Figure 1. Refer to Figure 1 for the location of trees identified for preservation, further protection notes, and the preservation detail. Tree protection fencing will need to be installed prior to construction to ensure trees identified for retention are not impacted by the development.

#### Trees 161, 164, 165, 187, 200 and 217-219

Encroachment into the minimum tree protection zones (mTPZ's) of Trees 161, 164, 165, 187, 200 and 217-219 will be required during the demolition of the existing dwelling. It is assumed that the existing gravel driveway will be used as an access route for

demolition. The following mitigation measures are to be followed to ensure the trees respond well to the development:

- Prior to demolition, designated tree protection fencing must be installed as shown in orange on Figure 1. Horizontal hoarding has been prescribed where the mTPZ's cannot be fully respected. Refer to Hoarding Detail shown on Figure 1 for specifications.
- The existing gravel driveway is to be used for access during demolition.
- The existing foundation is located within the mTPZ's of Trees 161, 164, 165, 187 and 200. The foundation is to be removed carefully using small machinery under the supervision of a Certified Arborist. Any exposed roots should be left intact.
- Retaining walls and steps are located within the mTPZ's of Trees 161, and 217-219. Designated tree protection fencing can be temporarily modified to allow person access during the demolition of the retaining wall. The existing retaining walls must be carefully demolished by hand or using small machinery (ie. Skidsteer) under the supervision of a Certified Arborist. Any exposed roots must remain intact. The area can be remediated using topsoil.
- Following demolition, the gravel driveway area can be remediated. The gravel must be carefully removed by hand, no below grade changes are permitted.
   Topsoil and sod can be used to remediate the area.

Please note that preservation planning is subject to change provided a detailed servicing and grading plan.

## **Summary and Recommendations**

Kuntz Forestry Consulting Inc. was retained by Almont Homes Inc. to complete a Tree Inventory and Preservation Plan as part of a development application for the property located at 1794 Appleview Road in Pickering, Ontario. A tree inventory was conducted and reviewed in the context of the proposed site plan.

The findings of the study indicate a total of 70 trees and three tree polygons on and within six metres of the subject property. The removal of 11 trees will be required to accommodate the proposed construction. All other trees can be saved provided appropriate tree protection measures are installed prior to the construction.

The following recommendations are suggested to minimize impact to trees identified for preservation. Refer to Figure 1 for the location of required tree preservation fencing and general Tree Protection Plan Notes, and the tree preservation fence detail.

- Tree protection barriers and fencing should be erected at locations as prescribed on Figure 1. All tree protection measures should follow the guidelines as set out in the tree preservation plan notes and the tree preservation fencing detail.
- No construction activity including surface treatments, excavations of any kind, storage of materials or vehicles, unless specifically outlined above, is permitted within the area identified on Figure 1 as a tree protection zone (TPZ) at any time during or after construction.

- Branches and roots that extend beyond prescribed tree protection zones that require pruning must be pruned by a qualified Arborist or other tree professional. All pruning of tree roots and branches must be in accordance with Good Arboricultural Standards.
- Site visits, pre, during, and post construction are recommended by either a certified consulting arborist (I.S.A.) or registered professional forester (R.P.F.) to ensure proper utilization of tree protection barriers. Trees should also be inspected for damage incurred during construction to ensure appropriate pruning or other measures are implemented.

Respectfully Submitted, **Kuntz Forestry Consulting Inc.** 

# Natasha Brooks

Natasha Brooks, B.B.R.M.(EM), CERPIT Ecologist, ISA Certified Arborist #ON-2906A, TRAQ

Email: natasha.brooks@kuntzforestry.ca

Phone: 289-837-1871 ext.108

#### <u>Limitations of Assessment</u>

Only the tree(s) identified in this report were included in the inventory. The assessment of the trees presented in this report has been made using accepted arboricultural techniques. These may include a visual examination taken from the ground of all the above-ground parts of the tree for structural defects, scars, external indications of decay such as fungal fruiting bodies, evidence of attack by insects, discoloured foliage, the condition of any visible root structures, the degree of lean (if any), the general condition of the trees and the identification of potentially hazardous trees or recommendations for removal (if applicable). Where trees could not be directly accessed (ie. due to obstructions, and/or on neighbouring properties), trees were assessed as accurately as possible from nearby vantage points.

Locations of trees provided in the report are determined as accurately as possible based on the best information available. If official survey information is not provided, tree location in the report may not be exact. In this case, if trees occur on or near property boundaries, an official site survey may be required to determine ownership utilizing specialized survey protocol to gain precise location.

Furthermore, recommendations made in this report are based on the site plans that have been provided at the time of reporting. These recommendations may no longer be applicable should changes be made to the site plan and/or grading, servicing, or landscaping plans following report submission.

Notwithstanding the recommendations and conclusions made in this report, it must be recognized that trees are living organisms, and their health and vigor constantly change over time. They are not immune to changes in site conditions or seasonal variations in the weather conditions. Any tree will fail if the forces applied to the tree exceed the strength of the tree or its parts.

Although every effort has been made to ensure that this assessment is reasonably accurate, the trees should be re-assessed periodically. The assessment presented in this report is valid at the time of inspection.

**Table 1. Tree Inventory** 

Location: 1794 Appleview Road Date: 1 August 2025 Surveyors: NB

Tree #	Common Name	Scientific Name	DBH	TI	cs	cv	CDB	DL	mTPZ	Comments	Action
116	Manitoba Maple	Acer negundo	25	F	F	G		2.0	1.8	Lean (L), epicormic branching (M)	Preserve
133	Manitoba Maple	Acer negundo	55	F	F	F- G		5.0	3.6	Union at 4m	Preserve
142	Manitoba Maple	Acer negundo	16	F	F	F- G		2.0	1.8	Lean (L), bowed (L)	Preserve
143	Sugar Maple	Acer saccharum	23	F	F- G	F- G		2.0	1.8	Stem wound (L), crook (L)	Preserve
144	White Spruce	Picea glauca	38	G	G	G		3.0	2.4		Preserve
145	Manitoba Maple	Acer negundo	15	F	F	F- G		1.0	1.8		Preserve
146	White Spruce	Picea glauca	40	G	G	G		2.0	2.4		Preserve
147	White Spruce	Picea glauca	34	G	G	G		2.0	2.4		Preserve
148	White Spruce	Picea glauca	35	G	G	G		2.0	2.4		Preserve
150	White Spruce	Picea glauca	34	G	G	G		2.0	2.4		Preserve
151	White Spruce	Picea glauca	29	G	G	G		2.0	1.8		Preserve
156	White Spruce	Picea glauca	25	G	G	G		2.0	1.8		Preserve
157	White Spruce	Picea glauca	22	G	G	F		2.0	1.8	Deadwood (L)	Preserve
158	White Spruce	Picea glauca	19	G	G	G		2.0	1.8		Preserve
159	White Spruce	Picea glauca	19	G	G	G		1.5	1.8		Preserve
160	White Spruce	Picea glauca	37	G	G	G		5.0	2.4		Preserve
161	White Spruce	Picea glauca	36	G	G	G		3.0	2.4		Preserve (Injure)
162	White Spruce	Picea glauca	72	G	G	G		5.0	4.8		Preserve
163	Apple species	Malus spp.	25	G	G	F		2.0	1.8	Deadwood (M), epicormic branching (M)	Preserve
164	White Spruce	Picea glauca	42	G	G	G		3.0	3.0		Preserve (Injure)
165	White Spruce	Picea glauca	35	G	G	G		2.5	2.4		Preserve (Injure)
166	White Spruce	Picea glauca	31	G	G	G		2.0	2.4		Preserve
167	White Spruce	Picea glauca	29	F	F	Р	60	2.0	1.8		Remove (Condition)

7

168	White Spruce	Picea glauca	17	G	G	G	1.5	1.8		Preserve
F	Manitoba Maple	Acer negundo	~29	F	F	F- G	3.0	1.8	Lean (M), Crook (M)	Preserve
169	Black Walnut	Juglans nigra	69	G	G	G	5.0	4.2		Preserve
170	Black Walnut	Juglans nigra	35	G	G	G	5.0	2.4		Remove
171	Black Walnut	Juglans nigra	27	G	F	G	3.0	1.8	Crook (L)	Remove
172	Black Walnut	Juglans nigra	27	G	G	G	3.0	1.8		Remove
173	Black Walnut	Juglans nigra	64	G	G	G	2.0	4.2		Remove
174	Black Walnut	Juglans nigra	21	G	G	G	5.0	1.8		Remove
175	Black Walnut	Juglans nigra	20	G	G	G	2.0	1.8		Remove
176	White Spruce	Picea glauca	16	G	G	G	0.5	1.8		Remove
177	Black Walnut	Juglans nigra	16	G	G	G	1.0	1.8		Remove
178	White Mulberry	Morus alba	28	G	F	F- G	2.0	1.8	Union at 2m, epicormic branching (L)	Preserve
179	Black Walnut	Juglans nigra	58	G	F	F- G	5.0	3.6	Poor form (L), crook (L), deadwood (L)	Remove
180	Silver Maple	Acer saccharinum	28	F	F	F- G	2.0	1.8	Union at 5m, one stem removed	Remove
181	White Spruce	Picea glauca	32	G	G	G	2.0	2.4		Remove
182	Manitoba Maple	Acer negundo	75	Р	P- F	F- G	5.0	4.8	Active stem failure, fruiting bodies (M), poor form (M)	Remove (Condition)
183	Black Walnut	Juglans nigra	44	G	G	G	4.0	3.0		Preserve
184	Little-leaf linden	Tilia cordata	56	F	F- G	F- G	4.0	3.6	Union at 2m, deadwood (L)	Preserve
185	Manitoba Maple	Acer negundo	48	F	F	P- F	5.0	3.0	Lean (L-M), epicormic branching (M), deadwood (M)	Remove (Condition)
186	White Spruce	Picea glauca	60	G	G	F- G	4.0	3.6	Deadwood (L)	Preserve
187	White Spruce	Picea glauca	58	G	G	G	4.0	3.6		Preserve (Injure)
188	Horsechestnut	Aesculus hippocastanum	25, 18	F- G	F- G	F- G	3.0	1.8	Union at 1m and 1.4m	Preserve
189	White Spruce	Picea glauca	45	G	G	F	3.0	3.0	Deadwood (M)	Preserve
191	Austrian Pine	Pinus nigra	44	G	G	G	2.5	3.0	_	Preserve
192	Austrian Pine	Pinus nigra	42	G	G	G	2.5	3.0		Preserve
193	Austrian Pine	Pinus nigra	40	G	G	G	2.5	2.4		Preserve
194	Austrian Pine	Pinus nigra	16	G	G	G	2.5	1.8		Preserve
195	Austrian Pine	Pinus nigra	32	G	G	G	2.5	2.4		Preserve

8

196	Silver Maple	Acer saccharinum	53	F	F	F- G	4.0	3.6	Union at 2m, stem wound with rot (L)	Preserve
197	Austrian Pine	Pinus nigra	35	G	G	G	3.0	2.4		Preserve
198	Austrian Pine	Pinus nigra	38	G	G	G	3.0	2.4		Preserve
199	Apple species	Malus spp.	40	P- F	F	P- F	3.0	2.4	Deadwood (H), union at 2m	Remove (Condition)
200	Manitoba Maple	Acer negundo	27	F	F	F	3.0	1.8	Lean (L), bowing (M)	Preserve (Injure)
212	White Spruce	Picea glauca	40				2.5	2.4		Preserve
213	Silver Maple	Acer saccharinum	31	F	F	F	3.0	2.4	Lean (L), bowed (M),	Preserve
214	Manitoba Maple	Acer negundo	45	F	F	F- G	3.5	2.4	Lean (M)	Preserve
215	White Spruce	Picea glauca	36	G	G	G	3.0	2.4		Preserve
216	White Spruce	Picea glauca	25	G	G	G	2.0	1.8		Preserve
217	White Spruce	Picea glauca	35	G	G	G	2.5	2.4		Preserve (Injure)
218	Norway Maple	Acer platanoides	40	G	G	G	2.5	2.4		Preserve (Injure)
219	White Spruce	Picea glauca	57	G	G	G	3.0	3.6		Preserve (Injure)
220	Manitoba Maple	Acer negundo	43	F	F	F	3.0	3.0	Lean (L), union at 3m	Preserve
221	Black Walnut	Juglans nigra	20	G	G	G	2.0	1.8		Preserve
Α	Sugar Maple	Acer saccharum	10	G	G	G	1.0	1.8		Preserve
В	Sugar Maple	Acer saccharum	8, 8, 3,	F	F	G	0.5	1.2		Preserve
С	Sugar Maple	Acer saccharum	5	G	G	G	0.5	1.2		Preserve
D	Manitoba Maple	Acer negundo	~29	F	F	F	1.0	1.8	Lean (M), crook (M)	Preserve
P1	Eastern White Cedar, Manitoba Maple	Thuja occidentalis, Acer negundo	10-15	G	G	G	0.5	1.8		Preserve
P2	Eastern White Cedar	Thuja occidentalis	10-15	G	G	G	 0.5	1.8		Preserve
P3	Eastern White Cedar	Thuja occidentalis	10-15	G	G	G	 0.5	1.8		Preserve

Codes		_					
DBH	Diameter at Breast Height	(cm)					
TI	Trunk Integrity	(G, F, P)					
CS	Crown Structure	(G, F, P)					
CV	Crown Vigor	(G, F, P)					
CDB	Crown Die Back	(%)					
DL	Dripline	(metres)					
~ = estimate; (VL) = very light; (L) = light;							
(M) = moderate; (H) = heavy							

## **Appendix A. Photographs of Trees**







Image 1. Tree 116

Image 2. Trees 133 and A-C

Image 3. Trees 145-156







Image 4. Trees 158 and 159

Image 5. Trees 164-169

Image 6. Trees 162 and 163








Image 7. Trees 170-177

Image 8. Trees 169, 185, 186

Image 9. Trees 180-182

13








Image 11. Tree 221 and P3